

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9808070292	DOC.DATE: 98/08/03	NOTARIZED: NO	DOCKET #
FACIL:50-388	Susquehanna Steam Electric Station, Unit 2, Pennsylv		05000388
AUTH.NAME	AUTHOR AFFILIATION		
KUCZYNSKI,G.J.	Pennsylvania Power & Light Co.		
RECIP.NAME	RECIPIENT AFFILIATION		
	Records Management Branch (Document Control Desk)		

SUBJECT: Forwards LER 98-010-00, describing reactor SCRAM on 980702, as result of IRM upscale trip caused by misoperation of IRM range switches.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 5
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
	PD1-2 PD	1	1	NERSSES,V	1	1
INTERNAL:	ACRS	1	1	AEOD/SPD/RAB	2	2
	AEOD/SPD/RRAB	1	1	FILE CENTER	1	1
	NRR/DE/ECGB	1	1	NRR/DE/EELB	1	1
	NRR/DE/EMEB	1	1	NRR/DRCH/HICB	1	1
	NRR/DRCH/HOHB	1	1	NRR/DRCH/HQMB	1	1
	NRR/DRPM/PECB	1	1	NRR/DSSA/SPLB	1	1
	RES/DET/EIB	1	1	RGN1 FILE 01	1	1
EXTERNAL:	L ST LOBBY WARD	1	1	LITCO BRYCE,J H	1	1
	NOAC POORE,W.	1	1	NOAC QUEENER,DS	1	1
	NRC PDR	1	1	NUDOCS FULL TXT	1	1

C
A
T
E
G
O
R
Y
1
D
O
C
U
M
E
N
T

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

George J. Kuczynski
General Manager-Susquehanna

Susquehanna Steam Electric Station
P.O. Box 467, Berwick, PA 18603
Tel. 717.542.3120 Fax 717.542.1949



August 3, 1998

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-388/98-010-00
PLA - 0004962 FILE R41-2

Docket No. 50-388
License No. NPF-22

Attached is Licensee Event Report 50-388/98-010-00, describing a Reactor SCRAM on July 2, 1998 on Susquehanna SES Unit 2. This SCRAM was a result of a Intermediate Range Monitor (IRM) Upscale Trip on both divisions, caused by misoperation of the IRM range switches. This event is reportable per 10CFR50.73(a)(2)(iv) as an Engineered Safety Feature actuation, in this case, the Reactor Protection System.

G. J. Kuczynski for
G. J. Kuczynski
General Manager - Susquehanna SES

Attachment

cc: Mr. H. J. Miller
Regional Administrator
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

cc: Mr. Kenneth M. Jenison
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P. O. Box 35
Berwick, PA 18603-0035

1/1
IE22

9808070292 980803
PDR ADDCK 05000388
S PDR

