



UNIT SHUTDOWNS

DOCKET NO. 50-388
 UNIT Two
 DATE 8/4/98
 COMPLETED BY K. A. Young
 TELEPHONE (717) 542-3251

REPORT MONTH June 1998

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Cause & Corrective Action to Prevent Recurrence
4	6-29-98	F	44.7	A*	3	<p>Unit 2 experienced an automatic reactor scram at 0319 June 29. During power ascension at 55% power the moisture separator drain tank had a high level which initiated a protective turbine trip, thus causing the automatic scram. General operating procedure for startup was changed to keep the drain lines open through 30% power during startups. Unit remained off line through the end of June.</p> <p>*Correction of previously submitted June 1998 Form. Reason for shutdown was equipment failure. See July shutdown number 5 for operational error.</p>



1.
 F. Forced
 S. Scheduled

2.
 Reason:
 A - Equipment Failure (Explain)
 B - Maintenance or Test
 C - Refueling
 D - Regulatory Restriction
 E - Operator Training & Licensee Exam
 F - Administrative
 G - Operational Error (Explain)

3.
 Method:
 1 - Manual
 2 - Manual Scram
 3 - Automatic Scram
 4 - Continuation from previous month
 5 - Other

9808190103 980810
 PDR ADDCK 05000387
 R PDR



14

SUSQUEHANNA STEAM ELECTRIC STATION

Docket Number: 50-388

Date: 6/9/98

Completed by: K. A. Young

Telephone: (717) 542-3251

Challenges to Main Steam Safety Relief Valves

None.

Changes to the Offsite Dose Calculation Manual

None.

Major Changes to Radioactive Waste Treatment System

None.

