

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9809090024 DOC. DATE: 98/09/03 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania 05000387
 AUTH. NAME: JONES, G.T. AUTHOR AFFILIATION: Pennsylvania Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Records Management Branch (Document Control Desk)

SUBJECT: Informs that inservice insp summary rept for SSES, Unit 1 will be submitted on 981019 due to listed reasons.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code - GL-89-04

NOTES:

05000387
 C
 A
 T
 E
 G
 O
 R
 Y
 1
 D
 O
 C
 U
 M
 E
 N
 T

	RECIPIENT		COPIES		
	ID CODE/NAME		LTR	ENCL	
	PD1-2 LA		1	1	
	NERSES, V		1	1	
INTERNAL:	ACRS		1	1	
	FILE CENTER 01		1	1	
	NUDOCS-ABSTRACT		1	1	
	RES/DET/EIB		1	1	
EXTERNAL:	LITCO ANDERSON		1	1	
	NRC PDR		1	1	
NOTES:			1	1	

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTR 15 ENCL 0



1-1-1

George T. Jones
Vice President - Engineering & Support
Tel. 610.774.7602 Fax 610.774.7797
E-mail: gtjones@papl.com

PP&L, Inc.
Two North Ninth Street
Allentown, PA 18101-1179
Tel. 610.774.5151
http://www.papl.com/



SEP 03 1998

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

**SUSQUEHANNA STEAM ELECTRIC STATION
NOTIFICATION OF DELAY IN ISSUANCE OF INSERVICE
INSPECTION SUMMARY REPORT
PLA-4972 FILE R41-2**

Docket No. 50-387

The purpose of this letter is to inform you that PP&L, Inc. will not be able to submit the Susquehanna SES Unit 1-10RIO inservice inspection summary report within the required ninety (90) day time frame.

Because of six (6) forced outages (total of 29 days) of both Susquehanna SES Units after completion of the Unit 1-10RIO, valuable resources originally allocated to the completion of documentation for the inservice inspection summary report were reassigned to outage efforts. The documentation in question is equipment repair and replacement forms (NIS-2 Forms) associated with maintenance work performed on Class 1, 2 and 3 systems. These resources were needed to help ensure that the outages were conducted safely and effectively so that the units could return to service. The unusually high number of outages (2 for Unit 1, 4 for Unit 2) utilized resources that otherwise would have been involved in the completion of the inservice inspection summary report. PP&L, Inc. needs an additional forty-five (45) days to make the submittal. The revised submittal date will be October 19, 1998. This request is only applicable to Unit 1 and will only apply to the Unit 1-10RIO.

1/0

Should you have any questions, please contact C.T. Coddington at (717) 542-3294.

A047

Sincerely,


G. T. Jones

copy: NRC Region I
Mr. K. Jenison, NRC Sr. Resident Inspector
Mr. V. Nerses, NRC Sr. Project Manager

9809090024 980903
PDR ADOCK 05000387
G PDR