



Robert F. Saunders  
Vice President - Nuclear Site Operations

Susquehanna Steam Electric Station.  
P.O. Box 467, Berwick, PA 18603  
Tel. 717.542.3256 Fax 717.542.1504  
rfsaunders@papl.com



November 2, 1998

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Station P1-137  
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 50-387/98-016-00  
PLA - 0005000 FILE R41-2

Docket No. 50-387  
License No. NPF-14

Attached is Licensee Event Report 50-387/98-016-00. This event was determined to be reportable per 10CFR50.73(a)(2)(iv) in that an automatic SCRAM occurred when the backup lockout relays for the generator tripped. The plant responded as expected following the SCRAM. There were no diesel starts or ECCS initiations. There were no safety consequences or compromises to public health and safety as a result of this event.

Robert F. Saunders  
Vice President - Nuclear Site Operations

Attachment

cc: Mr. H. J. Miller  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

cc: Sr. Resident Inspector  
U.S. Nuclear Regulatory Commission  
P. O. Box 35  
Berwick, PA 18603-0035

9811090100 9811027  
PDR ADOCK 05000387  
S PDR

IE22 / 11



23