

Robert F. Saunders
Vice President - Nuclear Site Operations

Susquehanna Steam Electric Station.
P.O. Box 467, Berwick, PA 18603
Tel. 717.542.3256 Fax 717.542.1504
rfsaunders@papl.com



MAY 24 1999

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-388/98-008-01
PLA - 0005028 FILE R41-2

Docket No. 50-388
License No. NPF-22

Attached is Licensee Event Report 50-388/98-008-01. This supplement provides a revision to the cause of failure of the Unit 2 "J" Main Steam Relief Valve (MSRV) acoustic monitor since the cause of the failure after further analysis was determined to be other than an intermittent short on the cabling. Also, all the corrective actions associated with this Licensee Event Report have been completed.

Robert F. Saunders
Vice President - Nuclear Site Operations

Attachment

cc: Mr. H. J. Miller
Regional Administrator
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Sam Hansell
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P. O. Box 35
Berwick, PA 18603-0035

9905270245 990524
PDR ADDCK 05000388
S PDR