

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

01 REPORT SOURCE L 6 0 5 0 0 0 2 4 9 7 1 1 0 4 7 8 8 1 1 3 0 7 8 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal weekend surveillance, while testing MSIV closure time, MSIV 3-203-2A
 03 closed 2.8 seconds after the initiation signal, which did not meet T.S. Table
 04 3.7.D.2 limits of $3 \leq T \leq 5$ sec. Event was of minimal safety significance
 05 because other MSIV closure times were within T.S. limits and valve did close. This
 06 event has occurred several times before at Dresden, most recently referenced under
 07 R.O. #50-249/1976-12.
 08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
9 10 11 12 13 18 19 20
 C D 11 E 12 B 13 V A I V E X 14 F 15 D 16

17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
21 22 23 24 26 27 28 29 30 31 32
 7 8 0 5 4 0 3 L 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
33 34 35 36 37 40 41 42 43 44 47
 E 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 C 6 6 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 MSIV 3-203-2A valve timing was out of adjustment. Speed control valve was adjusted
 11 3/8 turn and valve closed successfully in 4.1 sec. History of quarterly testing of
 12 MSIV's this cycle shows 2A valve closure times have gradually shortened, apparently
 13 resulting from normal packing wear. No further action deemed necessary. No previous
 14 similar events with this valve.

15 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
7 8 9 10 12 13 44 45 46 48
 F 28 0 5 2 29 NA 30 A 31 Operator Observation 32

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
7 8 9 10 11 44 45 48
 Z 33 Z 34 NA 35 NA 36

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
7 8 9 11 12 13 44
 0 0 0 37 Z 38 NA 39

18 PERSONNEL INJURIES NUMBER DESCRIPTION
7 8 9 11 12 44
 0 0 0 40 NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
7 8 9 10 44
 Z 42 NA 43

20 PUBLICITY ISSUED DESCRIPTION
7 8 9 10 44
 N 44 NA 45

781221 0252

NRC USE ONLY

NAME OF PREPARER Richard Ralph

PHONE: 422