

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 I L D R S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

0 1 REPORT SOURCE L 6 0 5 0 0 0 2 4 9 7 0 6 0 8 7 9 8 0 7 0 3 7 9 9  
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing weekly surveillance DIS 700-3, Source Range Monitor Calibration, SRM  
0 3 #21 Hi count was found to initiate a Rod Block at  $1.10 \times 10^5$  counts per second which is  
0 4 in violation of Tech Spec Limit of  $\leq 1.0 \times 10^5$  counts per second. The safety im-  
0 5 plications were minimal because the remaining SRM channels were all operative and found  
0 6 within the Dresden setpoint limit. This is the first occurrence of this nature on  
0 7 this unit.

0 9 SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE Q 15 VALVE SUBCODE Z 16  
8 9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER 7 9 21 22 EVENT YEAR 23 SEQUENTIAL REPORT NO. 0 1 5 24 26 OCCURRENCE CODE 0 3 27 29 REPORT TYPE L 30 31 REVISION NO. 0 32

ACTION TAKEN E 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER G 0 8 0 0 26  
33 34 35 36 37 40 41 42 43 44 47

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause is attributed to electronic instrument drift. SRM #21 was readjusted to  
1 1  $.97 \times 10^5$  cps, and DIS 700-3 was successfully completed. SRM's will continue to be  
1 2 tested weekly as per DIS 700-3.

1 5 FACILITY STATUS E 28 % POWER 0 9 6 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION DIS 700-3 32  
8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36  
8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39  
8 9 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41  
8 9 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43  
8 9 10 80

2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45  
8 9 10 80

7907100311

NAME OF PREPARER John Dunbar

PHONE: 489

NRC USE ONLY