

LICENSEE EVENT REPORT

CONTROL BLOCK: _____

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1	I	L	D	R	S	2	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	4	5
8	LICENSEE CODE					14	LICENSE NUMBER					25	LICENSE TYPE					30	CAT 58					57	58

1	L	0	5	0	0	0	2	3	7	7	0	1	0	6	8	0	8	0	1	3	0	8	0	9
8	REPORT SOURCE		DOCKET NUMBER					EVENT DATE					REPORT DATE					60	61	68	69	74	75	80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 While performing weekly turbine control valve exercising, the 1/2 scram on RPS Channel

3 A received from the closure of #3 turbine control valve would not reset. Unit load

4 was reduced to < 45% power to bypass the generator load reject scram as permitted by

5 T.S. Table 3.1.1. This event was of minimal safety significance since the other

6 control valves were operable. This is the first failure of this type at Dresden.

7

8

9	H	A	11	E	12	A	13	I	N	S	T	R	U	14	S	15	Z	16		
9	SYSTEM CODE		11	CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE					
17	LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
8	21		22		23		24		25		26									
18	19		20		21		22		23		24		25		26					
33	34		35		36		37		40		41		42		43		44		47	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 The micro switch which sends and resets the scram signal for the Vickers fast acting

1 solenoid was found failed in the tripped position. Switch was out of adjustment, sub-

2 sequently causing switch to fail. Switch replaced, adjusted and valve operated proper-

3 ly. Replacement of solenoids planned during refueling outage at which time all micro

4 switches will be checked.

5	E	0	8	3	29	N/A	30	B	31	Turbine Control Valve Exercising	32				
8	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY					DISCOVERY DESCRIPTION			
6	Z		Z		N/A		35					N/A			
8	9		10		11		12					13			
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		39		40					41		
7	0		0		0		37		Z		38		N/A		
8	9		10		11		12					13			
PERSONNEL EXPOSURES NUMBER		TYPE		DESCRIPTION		40		41					N/A		
3	0		0		0		40		41					N/A	
8	9		10		11		12					13			
PERSONNEL INJURIES NUMBER		DESCRIPTION		43		44					N/A				
9	Z		42		43		44					N/A			
8	9		10		11		12					13			
LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION		45		46					N/A				
9	Z		42		43		44					N/A			
8	9		10		11		12					13			
PUBLICITY ISSUED		DESCRIPTION		45		46					N/A				
0	N		44		45		46					N/A			
8	9		10		11		12					13			

8002080 NRC USE ONLY 375
68 69 80