

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1	I	L	D	R	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
8	9					14	15											25	26							57	CAT	58
LICENSEE CODE						LICENSE NUMBER													LICENSE TYPE									

DN'T

REPORT SOURCE L 6 0 5 0 0 0 2 3 7 7 0 1 0 6 8 0 8 0 1 3 0 8 0 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 While performing weekly turbine control valve exercising, the 1/2 scram on RPS Channel

3 A received from the closure of #3 turbine control valve would not reset. Unit load

4 was reduced to < 45% power to bypass the generator load reject scram as permitted by

5 T.S. Table 3.1.1. This event was of minimal safety significance since the other

6 control valves were operable. This is the first failure of this type at Dresden.

7

8

9		SYSTEM CODE H A		11	CAUSE CODE E		12	CAUSE SUBCODE A		13	COMPONENT CODE I N S T R U					14	COMP. SUBCODE S		15	VALVE SUBCODE Z		16																										
17		LER/RO REPORT NUMBER		EVENT YEAR 8 0		21	22	SEQUENTIAL REPORT NO. 0 0 1		24	OCCURRENCE CODE 0 3		28	REPORT TYPE I		30	REVISION NO. 0		32	ACTION TAKEN A		33	FUTURE ACTION C		34	EFFECT ON PLANT B		35	SHUTDOWN METHOD Z		36	HOURS 0 0 0 6		39	ATTACHMENT SUBMITTED N		41	NPRD-4 FORM SUB. N		42	PRIME COMP. SUPPLIER N		43	COMPONENT MANUFACTURER G 0 8 0				47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 The micro switch which sends and resets the scram signal for the Vickers fast acting
1 solenoid was found failed in the tripped position. Switch was out of adjustment, sub-
2 sequently causing switch to fail. Switch replaced, adjusted and valve operated proper-
3 ly. Replacement of solenoids planned during refueling outage at which time all micro
4 switches will be checked.

FACILITY STATUS								% POWER								OTHER STATUS								METHOD OF DISCOVERY								DISCOVERY DESCRIPTION							
E								0 8 3								N/A								B								Turbine Control Valve Exercising							
ACTIVITY CONTENT								AMOUNT OF ACTIVITY								LOCATION OF RELEASE																							
Z								Z								N/A								N/A															
PERSONNEL EXPOSURES								DESCRIPTION																															
NUMBER TYPE																																							
0 0 0								Z								N/A																							
PERSONNEL INJURIES								DESCRIPTION																															
NUMBER																																							
0 0 0																N/A																							
LOSS OF OR DAMAGE TO FACILITY								DESCRIPTION																															
TYPE																																							
Z																N/A																							
PUBLICITY								DESCRIPTION																															
ISSUED																																							
N																N/A																							

NRC USE ONLY

8002080

375