



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

February 6, 1980

Director of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Dresden Station Unit 3
Technical Specification Change
to Implement 10 CFR 50.59
Reload Licensing
NRC Docket No. 50-249

Reference (a): D. L. Peoples letter to Director
of Nuclear Reactor Regulation dated
December 10, 1979

Dear Sir:

Reference (a) submitted proposed changes to the License and Appendix A, Technical Specifications, to Facility Operating License DPR-25 to support future 10 CFR 50.59 reloads. A subsequent review of that submittal has indicated that several typographical errors were not corrected prior to transmittal.

Enclosed are corrected pages which will directly replace pages previously transmitted. Corrections have been made on pages 6, 7, 10, 12, 15, 16, 20, 21, 29, 46, 48, 62, 62A, and 63.

In addition, the original outage schedule has been moved up approximately 4 to 6 weeks due to jet pump operability problems requiring Dresden Unit 3 to shutdown and begin its refueling outage on February 2, 1980. This will require a more expeditious review than previously anticipated, in order to support a mid to late April startup.

Please address any questions you may have concerning this matter to this office.

One (1) signed original and thirty-nine (39) copies of this transmittal are provided for your use.

Very truly yours,

Robert F. Janecek

Robert F. Janecek
Nuclear Licensing Administrator
Boiling Water Reactors

*Acc
1/1*

Enclosure

P
8002120 331