

## LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

REPORT  
SOURCE

0 1 L 6 0 5 0 0 0 2 4 9 7 0 1 1 6 8 0 8 0 2 1 1 8 0 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation loss of sampling point automatic advance for the drywell  
0 3 oxygen analyzer was noted. The consequences were minimal since drywell oxygen concen-  
0 4 tration indication was still available and the sampling point could be advanced  
0 5 manually. Drywell oxygen concentration remained < 4% at all times during the event.  
0 6  
0 7  
0 8

0 9  
7 8 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
I D 11 E 12 A 13 M O T O R X 14 Z 15 Z 16  
9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER EVENT YEAR  
8 0 21 22

23 SHUTDOWN METHOD 24 SEQUENTIAL REPORT NO. 25 OCCURRENCE CODE 26 REPORT TYPE 27 REVISION NO.  
0 0 1 0 3 L 0  
23 24 26 27 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
A 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 B 1 3 5 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause for the loss of sampling point automatic advance was the electrical failure  
1 1 of the stepping switch motor, Beckman Inst. Part No. 808376. The stepping switch  
1 2 motor was replaced and full sampling point automatic advance was restored.  
1 3  
1 4

1 5 FACILITY STATUS 16 % POWER 17 OTHER STATUS 18 METHOD OF DISCOVERY 19 DISCOVERY DESCRIPTION  
E 28 0 6 6 29 NA A 31 Operator Observation  
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT 17 RELEASED OF RELEASE 18 AMOUNT OF ACTIVITY 19 LOCATION OF RELEASE  
Z 33 Z 34 NA NA  
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES 18 NUMBER 19 TYPE 20 DESCRIPTION 21  
0 0 0 37 Z 38 NA  
7 8 9 11 12 13 80

1 8 PERSONNEL INJURIES 19 NUMBER 20 DESCRIPTION 21  
0 0 0 40 NA  
7 8 9 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY 20 TYPE 21 DESCRIPTION 22  
Z 42 NA  
7 8 9 10 80

2 0 PUBLICITY 21 ISSUED 22 DESCRIPTION 23  
N 44 NA  
7 8 9 10 80

NAME OF PREPARER Ray Magrow

PHONE: X-526

8002200586

Dupe

7-926