ICENSEE BECKENGINEERING ROUTE 30-RR-1 BOX 27 JAMAICA, VERMONT 05343	2. REGIONAL OFFI	SPECTION	
LICENSEE		BRECTION	
	2. REGIONAL OFFI		
ROUTE 30- RR-1 BOX 27		CE	
	REGIO	I I LEAR REGULATORY COMMISSIO	
NAMAICA VERION / US ST)	475 ALI	ENDALE ROAD	
EPORT NUMBER(S) 97-001	KING O	F PRUSSIA PA 19406-1415	
DOCKET NUMBER(S) 4. LICENSE NUMBER(5. DATE(S) OF INSPECTION	
30-34464 44-303	294-01	NOVEMBER 19,	1997
ICENSEE: he inspection was an examination of the activities conducted under you	our license as they relate to	radiation safety and to compliance w	ith the Nuclear
egulatory Commission (NRC) rules and regulations and the conditions	s of your license. The ins	pection consisted of selective examination	
nd representative records, interviews with personnel, and observations 1. Based on the inspection findings, no violations were identifi		spection findings are as follows:	* 1
	neu.		
 The violation(s), specifically described to you by the inspec non-repetitive, and corrective action was or is being taken, a 			
		ing the following requirement(s):	
3. During this inspection certain of your activities, as describe			and are being cit
This form is a NOTICE OF VIOLATION, which is required	to be posted in accordan	ce with 10 CFR 19.11.	
			. * *
	`		
	· · · · ·		
	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	
1997 - <u></u>			
	· · · · · · · · · · · · · · · · · · ·		
			101
			s 100 1851
9712010012 971119	<u>.</u>		
PDR ADDCK 03034464			3 •
PDR			
		RETURN ORIGINAL	*
DESIGNATED ORIGINAL	IE 07	REGION I	
Certified by: In a Realine			
		No.	
hereby state that, within 30days, the actions described by me to the In ctions is made in accordance with the requirements of 10 CFR 2.201 ((corrective steps already t	prrect the violations identified. This staken, corrective steps which will be ta	atement of correct ken, date when fu
ompliance will be achieved). I understand that no further written respo			*
		SIGNATURE	DATE
LICENSEE			

1

, **t**