

Docket No. 050-237
 UNIT NAME Dresden Unit 2
 DATE July 1, 1993
 Completed By Kevin Sykes
 Telephone (815) 942-2920

3.5 UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH June, 1993

NO.	DATE	TYPE(1)	DURATION (HOURS)	REASON (2)	METHOD OF SHUTTING DOWN REACTOR(3)	LICENSEE EVENT REPORT #	SYSTEM CODE(4)	COMPONENT CODE(5)	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
2	06/20/93	F	28.28	(A)	(4)	N/A	3200	RFP	2 C RFP seal cooler line leak. Initiated investigation under PIR 12-2-93-092 (237-200-93-09200). 2 B RFP was already out of service at that time thus a Power reduction was required.
1	06/18/93	S	11.85	(B)	(4)	N/A	201	RCP	Reduced Load to implement draining of oil from 2A and 2B Recirc. pumps due to high level.

(1)
 F: FORCED
 S: SCHEDULED

(2)
 Reason:
 A Equipment Failure (Explain)
 B Maintenance or Test

C. Refueling
 D Regulatory Restriction
 E Operator Training & License Exam
 F Administrative
 G Operational Error
 H Other (Explain)(4)

(3)
 Method:
 1. Manual
 2. Manual Scram
 3. Automatic Scram
 4. Other (Explain)
 5. Load Reduction

(4)
 Exhibit G Instructions for Preparation of Data
 Entry Sheets for Licensee Event Reports (LER) File
 (NUREG-0161)

(5)
 Exhibit I Same Source as above.

9307160287 930714
 PDR ADDCK 05000237
 R PDR