

May 31, 1994

GFSLTR 94-0175

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Licensee Event Report 93-017-01, Docket 50-249 is being submitted to correct typographical errors found in the original report.

Sincerely,

Gary F. Spedl Station Manager Dresden Station

GFS/GP:cfq

**Enclosure** 

cc: J. Martin, Regional Administrator, Region III

NRC Resident Inspector's Office

File/NRC

File/Numerical

gfs94\0175.94

9406080316 940531 PDR ADDCK 05000249 S PDR JE32 /

## DAP FORM 02-08C SUPPLEMENTAL REPORT TO LER

DVR NO.					SYSTEM AFFECTED		
	STA	UNIT	YEAR	NO.			
D	- 12	- 3	- 93 -	017	2300	······	
PART 1 TITLE OF EVENT					OCCURRED		
High Pressure Coolant Injection Declared Inoperable Due to Broken Room Cooler Drive Belts					11/01/93	2250	
					DATE	TIME	
REASON FOR SUPPLEMENTAL REPORT							
To correct typographical errors found in the original report.							
PART 2 ACCEPTANCE BY STATION REVIEW					In Hander Pet Ho	A.P	
DATE				•	6.2-94 1 6RI	194	
		TAL REPORT . D FOR DISTRI		ND .	Show In	6/2/74	
			·		STATION MANAGER	DATE	