

Commonwealth Edison

Dresden Nuclear Power Station 6500 North Dresden Road Morris, Illinois 60450 Telephone 815/942-2920

August 5, 1994

GFSLTR 94-0261

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Licensee Event Report 94-005-01, Docket 05000237, is being submitted in accordance with Technical Specification 6.6, NUREG 1022 and 10CFR50.73(a)(2)(iv). This supplement is being issued with added corrective actions as required after engineering evaluation.

Sincerely,

Gary F. Spedl/ Station Manager

Dresden Station

GFS/MB:cfq

Enclosure

cc: J. Martin, Regional Administrator, Region III

NRC Resident Inspector's Office

File/NRC

File/Numerical

940902029B 940805 PDR ADDCK 05000249 S PDR 1827

DAP FORM 02-08C SUPPLEMENTAL REPORT TO LER

DVR NO.		SYSTEM AFFECTED	
STA UNIT YEAR	NO.		
D - 12 - 3 - 94 - (001-01		÷ .
PART 1 TITLE OF EVENT		OCCURRED	
	•		•
Containment Atmosphere Monitor Check Valve 3-2499-28B Exceeded Technical	,		
Specification Leakage Limit of 0.6 L. Due to Foreign Materials on Seat		02/26/94	1330
		DATE	TIME
REASON FOR SUPPLEMENTAL REPORT			
Added corrective actions as required after engi	neering	evaluation.	, se - S
PART 2			
ACCEPTANCE BY STATION REVIEW	. •		
DATE			
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION		*See attached DAP 10-01 Rev 16 Form 10-1A and 10-1B for Approval Signatures	·
		STATION MANAGER	DATE