

October 24, 1994

Mr. D. L. Farrar
Manager, Nuclear Regulatory Services
Commonwealth Edison Company
Executive Towers West III, Suite 500
1400 OPUS Place
Downers Grove, IL 60515

DISTRIBUTION

Docket File	NRC & Local PDRs	OGC
PDIII-2 r/f	JZwolinski	JRoe
CMoore	RCapra	
WRackley	JStang	
CPatel	EAdensam	
ACRS(10)	BClayton, RIII	

SUBJECT: DRESDEN STATION, UNITS 2 AND 3; LASALLE STATION, UNITS 1 AND 2;
QUAD CITIES, UNITS 1 AND 2 - RESPONSE TO NRC BULLETIN 93-02,
SUPPLEMENT 1, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING SUCTION
STRAINERS" (TAC NOS. M89284, M89285, M89293, M89294, M89306 AND
M89307)

Dear Mr. Farrar:

This letter acknowledges receipt of your response dated April 19, 1994, to NRC Bulletin 93-02, Supplement 1 (Bulletin). The Bulletin was issued February 18, 1994, to all Boiling Water Reactor (BWR) licensees for action and to all Pressurized Water Reactor (PWR) licensees for information. The purpose of the Bulletin was to inform BWR and PWR licensees about the vulnerability of ECCS suction strainers in BWRs and containment sumps in PWRs to clogging during the recirculation phase of a loss-of-coolant accident (LOCA), to request that BWR licensees take the appropriate actions to ensure reliability of the ECCS in view of the information discussed in this Bulletin Supplement, and to require that BWR licensees report to the NRC on the requested actions taken. Your response adequately addressed the actions you have taken to assure the operability of ECCS recirculation. Please retain any records of your actions in response to this Bulletin, as subsequent inspection activities may be conducted in regard to this issue.

Should you have any questions, please contact me at (301) 504-3016 or the lead Project Manager for this issue, M. David Lynch, at (301) 504-3023.

Sincerely,

Original Signed By:

Robert M. Pulsifer, Project Manager
Project Directorate III-2
Division of Reactor Projects - III/IV
Office of Nuclear Reactor Regulation

9410280010 941024
PDR AD0CK 05000237
Q PDR

Docket Nos. 50-237, 50-249, 50-254,
50-265, 50-373 and 50-374

cc: see next page

*See previous concurrence

OFC	LA:PDIII-2	PM:PDIII-2	PM:PDIII-2	PM:PDIII-2	D:PDIII-2	
NAME	CMOORE*	RPULSIFER <i>RP</i>	JSTANG*	WRECKLEY*	RCAPRA <i>Ra</i>	
DATE	08/31/94	08/31/94	10/20/94	10/20/94	10/24/94	/ /94
COPY	YES/NO	YES/NO	YES/NO	YES/NO	(YES/NO)	YES/NO

DOCUMENT NAME: G:\CMRCJR\QUAD\QC89306.LTR

260085 OFFICIAL RECORD COPY

NRC FILE CENTER COPY

Mr. D. L. Farrar
Manager, Nuclear Regulatory Services
Commonwealth Edison Company
Executive Towers West III, Suite 500
1400 OPUS Place
Downers Grove, IL 60515

DISTRIBUTION

Docket File NRC & Local PDRs OGC
PDIII-2 r/f JZwolinski JRoe
CMoore RCapra
WRackley JStang
CPatel EAdensam
ACRS(10) BClayton, RIII

SUBJECT: DRESDEN STATION, UNITS 2 AND 3; LASALLE STATION, UNITS 1 AND 2;
QUAD CITIES, UNITS 1 AND 2 - RESPONSE TO NRC BULLETIN 93-02,
SUPPLEMENT 1, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING SUCTION
STRAINERS" (TAC NOS. M89284, M89285, M89293, M89294, M89306 AND
M89307)

Dear Mr. Farrar:

This letter acknowledges receipt of your response dated April 19, 1994, to NRC Bulletin 93-02, Supplement 1 (Bulletin). The Bulletin was issued February 18, 1994, to all Boiling Water Reactor (BWR) licensees for action and to all Pressurized Water Reactor (PWR) licensees for information. The purpose of the Bulletin was to inform BWR and PWR licensees about the vulnerability of ECCS suction strainers in BWRs and containment sumps in PWRs to clogging during the recirculation phase of a loss-of-coolant accident (LOCA), to request that BWR licensees take the appropriate actions to ensure reliability of the ECCS in view of the information discussed in this Bulletin Supplement, and to require that BWR licensees report to the NRC on the requested actions taken. Your response adequately addressed the actions you have taken to assure the operability of ECCS recirculation. We will await your report on completion of the requested actions. Please retain any records of your actions in response to this Bulletin, as subsequent inspection activities may be conducted in regard to this issue.

Should you have any questions, please contact me at (301) 504-3025 or the lead Project Manager for this issue, M. David Lynch, at (301) 504-3023.

Sincerely,

Chandu P. Patel, Project Manager
Project Directorate III-2
Division of Reactor Projects - III/IV
Office of Nuclear Reactor Regulation

Docket Nos. 50-237, 50-249, 50-254,
50-265, 50-373 and 50-374

cc: see next page

OFC	LA: PDIII-2	PM: PDIII-2	PM: PDIII-2	PM: PDIII-2	D: PDIII-2	
NAME	CMOORE	CPATEL	JSTANG	WRECKLEY	RCAPRA	
DATE	8/31/94	8/15/94	10/20/94	10/20/94	/ /94	/ /94
COPY	(YES/NO)	(YES/NO)	(YES/NO)	(YES/NO)	YES/NO	YES/NO

DOCUMENT NAME: G:\CMRCJR\QUAD\QC89306.LTR

OFFICIAL RECORD COPY

October 24, 1994

Mr. D. L. Farrar
Manager, Nuclear Regulatory Services
Commonwealth Edison Company
Executive Towers West III, Suite 500
1400 OPUS Place
Downers Grove, IL 60515

DISTRIBUTION

Docket File	NRC & Local PDRs	OGC
PDIII-2 r/f	JZwolinski	JRoe
CMoore	RCapra	
WRackley	JStang	
CPatel	EAdensam	
ACRS(10)	BClayton, RIII	

SUBJECT: DRESDEN STATION, UNITS 2 AND 3; LASALLE STATION, UNITS 1 AND 2;
QUAD CITIES, UNITS 1 AND 2 - RESPONSE TO NRC BULLETIN 93-02,
SUPPLEMENT 1, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING SUCTION
STRAINERS" (TAC NOS. M89284, M89285, M89293, M89294, M89306 AND
M89307)

Dear Mr. Farrar:

This letter acknowledges receipt of your response dated April 19, 1994, to NRC Bulletin 93-02, Supplement 1 (Bulletin). The Bulletin was issued February 18, 1994, to all Boiling Water Reactor (BWR) licensees for action and to all Pressurized Water Reactor (PWR) licensees for information. The purpose of the Bulletin was to inform BWR and PWR licensees about the vulnerability of ECCS suction strainers in BWRs and containment sumps in PWRs to clogging during the recirculation phase of a loss-of-coolant accident (LOCA), to request that BWR licensees take the appropriate actions to ensure reliability of the ECCS in view of the information discussed in this Bulletin Supplement, and to require that BWR licensees report to the NRC on the requested actions taken. Your response adequately addressed the actions you have taken to assure the operability of ECCS recirculation. Please retain any records of your actions in response to this Bulletin, as subsequent inspection activities may be conducted in regard to this issue.

Should you have any questions, please contact me at (301) 504-3016 or the lead Project Manager for this issue, M. David Lynch, at (301) 504-3023.

Sincerely,

Original Signed By:

Robert M. Pulsifer, Project Manager
Project Directorate III-2
Division of Reactor Projects - III/IV
Office of Nuclear Reactor Regulation

Docket Nos. 50-237, 50-249, 50-254,
50-265, 50-373 and 50-374

cc: see next page

*See previous concurrence

OFC	LA:PDIII-2	PM:PDIII-2	PM:PDIII-2	PM:PDIII-2	D:PDIII-2	
NAME	CMOORE*	RPULSIFER <i>RP</i> *	JSTANG*	WRECKLEY*	RCAPRA <i>Ra</i>	
DATE	08/31/94	08/31/94	10/20/94	10/20/94	10/24/94	1 / 94
COPY	YES/NO	YES/NO	YES/NO	YES/NO	(YES)/NO	YES/NO

DOCUMENT NAME: G:\CMRCJR\QUAD\QC89306.LTR

OFFICIAL RECORD COPY

Mr. D. L. Farrar
Commonwealth Edison Company

Dresden Nuclear Power Station
Unit Nos. 2 and 3

cc:

Michael I. Miller, Esquire
Sidley and Austin
One First National Plaza
Chicago, Illinois 60690

Mr. G. Spedl
Plant Manager
Dresden Nuclear Power Station
6500 North Dresden Road
Morris, Illinois 60450-9765

U. S. Nuclear Regulatory Commission
Resident Inspectors Office
Dresden Station
6500 North Dresden Road
Morris, Illinois 60450-9766

Regional Administrator
U. S. NRC, Region III
801 Warrenville Road
Lisle, Illinois 60532-4351

Illinois Department of Nuclear Safety
Office of Nuclear Facility Safety
1035 Outer Park Drive
Springfield, Illinois 62704

Chairman
Grundy County Board
Administration Building
1320 Union Street
Morris, Illinois 60450

Mr. D. L. Farrar
Commonwealth Edison Company

LaSalle County Station
Unit Nos. 1 and 2

cc:

Phillip P. Steptoe, Esquire
Sidley and Austin
One First National Plaza
Chicago, Illinois 60603

Robert Cushing
Chief, Public Utilities Division
Illinois Attorney General's Office
100 West Randolph Street
Chicago, Illinois 60601

Assistant Attorney General
100 West Randolph Street
Suite 12
Chicago, Illinois 60601

Michael I. Miller, Esquire
Sidley and Austin
One First National Plaza
Chicago, Illinois 60690

Senior Resident Inspector
LaSalle County Station
U. S. Nuclear Regulatory Commission
2605 N. 21st Road
Marseilles, Illinois 61341-9756

Chairman
LaSalle County Board of Supervisors
LaSalle County Courthouse
Ottawa, Illinois 61350

Attorney General
500 South 2nd Street
Springfield, Illinois 62701

Chairman
Illinois Commerce Commission
Leland Building
527 East Capitol Avenue
Springfield, Illinois 62706

Illinois Department of Nuclear Safety
Office of Nuclear Facility Safety
1035 Outer Park Drive
Springfield, Illinois 62704

Regional Administrator
U. S. NRC, Region III
801 Warrenville Road
Lisle, Illinois 60532-4351

LaSalle Station Manager
LaSalle County Station
Rural Route 1
P.O. Box 220
Marseilles, Illinois 61341

Mr. D. L. Farrar
Commonwealth Edison Company

Quad Cities Nuclear Power Station
Unit Nos. 1 and 2

cc:

Mr. Stephen E. Shelton
Vice President
Iowa-Illinois Gas and
Electric Company
P. O. Box 4350
Davenport, Iowa 52808

Michael I. Miller, Esquire
Sidley and Austin
One First National Plaza
Chicago, Illinois 60690

Mr. Guy Campbell
Station Manager
Quad Cities Nuclear Power Station
22710 206th Avenue North
Cordova, Illinois 61242

Quad Cities Resident Inspectors Office
U. S. Nuclear Regulatory Commission
22712 206th Avenue North
Cordova, Illinois 61242

Chairman
Rock Island County Board
of Supervisors
1504 3rd Avenue
Rock Island County Office Bldg.
Rock Island, Illinois 61201

Illinois Department of Nuclear Safety
Office of Nuclear Facility Safety
1035 Outer Park Drive
Springfield, Illinois 62704

Regional Administrator
U. S. NRC, Region III
801 Warrenville Road
Lisle, Illinois 60532-4351