Commonwealth Edison Impany Dresden Generating Station 6500 North Dresden Road Morris, IL 60450 Tel 815-942-2920



July 21, 1995

TPJLTR 95-0081

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Licensee Event Report 95-002, Docket 50-237 is being submitted as required by Technical Specification 6.6 and 10CFR50.73(a)(2)(ii).

This revised report is submitted to describe the results of the root cause investigation into the Local Leak Rate Test (LLRT) failure of Drywell Air Sample Valve 2-9205B.

Sincerely,

Thomas 'P. Joyce

Site Vice President

TPJ/MG:pt

Enclosure

cc: H. Miller, Regional Administrator, Region III

NRC Resident Inspector's Office

File/NRC

File/Numerical

250131

TPJ95\0081.95

9507250146 950721 PDR ADDCK 05000237 S PDR

A Unicom Company

1522 ||