

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



October 31, 1995

PGHLTR 95-0027

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Licensee Event Report 95-007, Supplement 1, Docket 50-249 is being submitted pursuant to 10CFR50.73(a)(2)(i)(B) and 10CFR50.73(a)(2)(ii), the reporting of any operation or condition prohibited by the Plant's Technical Specifications.

This supplement provides the cause of the failure of Main Steam Line Drain gate valves 3-220-1 and 3-220-2 and Reactor Water Cleanup Suction Valve 3-1201-1. In addition, this supplement addresses the safety significance of the failures and corrective actions taken.

This letter contains the following commitment:

Additional evaluations are being performed to refine the dose rate calculations to determine whether or not either GDC 19 limits or 10CFR100 limits would have been exceeded (NTS 249-180-95-00704).

Sincerely,

Peter G. Holland
Regulatory Assurance Supervisor

PGH/MM:pt

Enclosure

cc: H. Miller, Regional Administrator, Region III
NRC Resident Inspector's Office
File/NRC
File/Numerical

L:\8360\8301\pghltr_95\0027.95

9511030109 951031
PDR ADOCK 05000249
S PDR

A Unicom Company