

Commonwealth Edison Company  
Dresden Generating Station  
6500 North Dresden Road  
Morris, IL 60450  
Tel 815-942-2920

**ComEd**

February 27, 1996


JSP Ltr. #96-0021

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Licensee Event Report 95-19, Docket 50-237, Revision 1 is being submitted pursuant to 10CFR50.73(a)(2)(v)(A), any event or condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to shutdown the reactor and maintain it in a safe shutdown condition. The LER Supplement is being provided to provide the root cause of the event and additional corrective actions.

This correspondence contains the following commitments:

1. A review of the new modification process will be performed to assure changes made in 1986 are still in place. (237-180-95-01901S1)
2. A sampling of modifications designed by the same A/E and/or reviewed by the same cognizant ComEd engineers (as well as others) prior to the 1986 modification process improvements will be reviewed, with emphasis on single failure and system interactions. (237-180-95-01902S1)

  
J. Stephen Perry  
Vice President  
BWR Operations

Enclosure

cc: H. Miller, Regional Administrator, Region III  
NRC Resident Inspector's Office  
File/NRC  
File/Numerical

9603040285 960227  
PDR ADOCK 05000237  
S PDR

040083

LEZZ  
11