Commonwealth Edison Dresden Generating State 6500 North Dresden Road Morris. IL 60450 Tel 815-942-2920



March, 28 1996

JSP Ltr. #96-0040

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Licensee Event Report 94-007, Revision 1, Docket 50-237 is being submitted pursuant to 10CFR50.73(a)(2)(x) which requires the reporting of any event that posed an actual threat to the safety of the nuclear power plan or significantly hampered site personnel in the performance of duties necessary to the safe operation of the nuclear power plant including fires, toxic gas releases, or radioactive releases. This supplemental report is provided to update corrective actions for the event.

This correspondence contains the following commitments:

- 1. To further enhance the Control Room HVAC operation the automatic isolation function of the Control Room HVAC intake upon a high radiation signal modification will be pursued per Dresden Administration Procedure (DAP) 05-02, Issues Management Program, (2371809400703S1).
- 2. A review of the station procedures for operation of the Control Room HVAC following design basis events will be performed to verify appropriate actions are specified (2371809600301).

Sincerely,

J Stephen Perry Vice President BWR Operations

Enclosure

cc: H. Miller, Regional Administrator, Region III

NRC Resident Inspector's Office

File/NRC
File/Numerical

9604020098 960328 PDR ADDCK 05000237 JE22 /