

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



March 29, 1996

JSP Ltr. #96-0051


U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Enclosed is Licensee Event Report 96-002, Docket 50-249, which is being submitted pursuant to 10CFR50.73(a)(2)(i)(B), any operation or condition prohibited by the plant's Technical Specifications and 10CFR50.73(a)(2)(v), any event or condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident.

This correspondence contains the following commitments:

1. An inspection plan will be developed to evaluate the materiel condition of the drain line downstream from valve 2-2301-54 to valves AOV 2-2301-29 and AOV 2-2301-28 to determine if there are any additional instances of pipe wall thinning. Conditions which are determined to be unacceptable will be corrected with a material less susceptible to flow accelerated corrosion. (2491809600201)
2. An inspection plan will be developed to evaluate the materiel condition of the drain line downstream from valve 3-2301-55 to valves AOV 3-2301-29 and AOV 3-2301-28 to determine if there are any additional instances of pipe wall thinning. Conditions which are determined to be unacceptable will be corrected with a material less susceptible to flow accelerated corrosion. (2491809600202)

Sincerely,



J. Stephen Perry
Vice President
BWR Operations

Enclosure

cc: H. Miller, Regional Administrator, Region III
NRC Resident Inspector's Office

9604050225 960329
PDR ADDOCK 05000249
S PDR

