

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



May 16, 1996

JSPLTR #96-0075


U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Enclosed is Licensee Event Report 96-002, Docket 50-237 which is being submitted pursuant to 10 CFR 50.73(a)(2)(i) (A), and requires that the completion of any nuclear plant shutdown required by the plant's Technical Specification (TS) will be reported.

This correspondence contains the following commitments:

1. Permanent repair of the Main Steam drain bypass line orifice plate will be performed. (2371809600201)
2. Engineering will relocate the Pt.1 thermocouple away from the floor slab and onto the elbow in the torus to provide a more representative indication of fluid temperature in the HPCI piping in the Torus area. (2371809600202)
3. A hole will be drilled in the HPCI MO2-2301-8 valve disc eliminating the valve pressure binding concerns. (2371809600203)

Sincerely,


J. Stephen Perry
Site Vice President
Dresden Station

Enclosure

cc: H. Miller, Regional Administrator, Region III
NRC Resident Inspector's Office
Illinois Department of Nuclear Safety

200096

9605200337 960516
PDR ADOCK 05000237
S PDR

200096
1/1