

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



August 27, 1996

JSPLTR #96-140

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Enclosed is Licensee Event Report 96-012, Docket 50-237 which is being submitted pursuant to 10 CFR 50.73(a)(2)(iv), which requires the reporting of any event or condition which results in manual or automatic actuation of any Engineered Safety Feature (ESF).

This correspondence contains the following commitments:

1. This event will be covered during an Operations Lessons Learned lecture, which will stress the importance of self checking prior to taking action and prompt reporting of personnel errors to station management. (2371809601201)
2. Dresden Station has assembled a committee to evaluate Self-Check performance. The committee will provide an output report with recommendations to correct self check errors to the Operations Manager for consideration and implementation. (2371809601202)
3. The Operations Manager will revise and implement a change to the Operations Standards requiring enhanced communications prior to manipulation of any Control Room controls which perform multiple functions. (2371809601203)

If you have any questions, please contact Pete Holland, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,

J. Stephen Perry
J. Stephen Perry
Site Vice President
Dresden Station

Enclosure

cc: A. W. Beach, Regional Administrator, Region III
NRC Resident Inspector's Office
Illinois Department of Nuclear Safety

030100

9609050152 960827
PDR ADOCK 05000237
S PDR

A Unicom Company

JK:2/1