

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



October 7, 1996

JSPLTR #96-0184

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555


Enclosed is Licensee Event Report 96-012, Docket 50-249 which is being submitted pursuant to 10 CFR 50.73(a)(2)(v)(D) which requires the reporting of any condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident.

This correspondence contains the following regulatory commitments:

1. Review will be performed of other station procedures which check time delay relays and revise them as required to ensure that the testing methodology is appropriate for the installed configurations. (2371809601201)
2. Perform a performance monitoring program for the ATWS relays to verify that the relays are performing adequately using the new testing methodology. This will involve increasing the frequency of checking the time delay of these relays for performance trending. Program will last for one year. (2371809601202)

If you have any questions, please contact Pete Holland, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension 2714.

Sincerely,


J. Stephen Perry
Site Vice President
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office
Illinois Department of Nuclear Safety

9610160313 961007
PDR ADOCK 05000249
S PDR

1/1
IE22