

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



October 7, 1996

JSPLTR #96-0181

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555


Enclosed is Licensee Event Report 96-013, Docket 50-249 which is being submitted pursuant to 10 CFR 50.73(a)(2)(iv), which requires the reporting of any event or condition which results in manual or automatic actuation of any Engineered Safety Feature (ESF).

This correspondence contains the following regulatory commitments:

1. A station procedure will be developed and implemented which addresses ComEd general safety requirements along with additional site specific issues during maintenance evolutions. The Station & Property Loss Prevention Team will be included in the procedure development. (2491809601301)
2. The maintenance prejob briefing checklist, included in Dresden Administrative Procedure 15-06, will be revised to include emphasis on safety barriers, floor plug removal and hatchway openings. (2491809601302)
3. The proper use of Safety Rope and Barriers will be added to the Safety Module for Nuclear General Employee Training. (2491809601303)

If you have any questions, please contact Pete Holland, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


Stephen Perry
Site Vice President
Dresden Station

Enclosure

160092

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office
Illinois Department of Nuclear Safety

9610160380 961007
PDR ADOCK 05000249
S PDR

A Unicom Company

1/1
Le22