

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



December 11, 1996

JSPLTR #96-0233

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555


Enclosed is Licensee Event Report 96-020, Docket 50-237, which is being submitted pursuant to 10CFR50.73 (a)(2)(v)(B)&(D) which requires that the licensee report any event or condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to: remove residual heat, or mitigate the consequences of an accident.

This correspondence contains the following commitments:

1. A license amendment will be submitted resolving the issues identified in this report on the Low Pressure Coolant Injection and Containment Cooling Service Water systems. (2371009620100.40)
2. A review will be conducted on the design parameters of affected systems and components to ensure that an increase in peak suppression pool temperature does not adversely impact their safety function. (23722596R12-96144A)
3. The results of the root cause investigation and any significant corrective actions will be reported in a supplement to this LER. (2371809602001)

If you have any questions, please contact Pete Holland, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


J. Stephen Perry
Vice President
BWR Operations

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office

9612180035 961211
PDR ADOCK 05000237
S PDR