

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



April 21, 1997

JSPLTR #97-0078

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Enclosed is Licensee Event Report 97-002, Docket 50-249, which is being submitted pursuant to 10CFR50.73(a)(2)(i)(B), which requires the reporting of any operation prohibited by Technical Specifications.

This correspondence contains the following commitments:

1. Operations Management will provide clarification on the accepted methodology for performance of shift turnover active Limiting Condition for Operation (LCO) reviews. This activity now requires that the task be performed using the actual Dresden Administrative Technical Requirements or Technical Specifications document, not the computerized LCO log. (2491809700201)
2. The Unit Supervisor will revise the appropriate Dresden Administrative Procedures for shift turnover requirements, clarifying the acceptable methodology for task performance. (2491809700202)
3. Initiate a Trend Problem Identification Form (PIF) on the topic of Human Error in the performance of Technical Specification and Dresden Administrative Technical Requirement compliance, citing that we recognize that our performance is cyclic and perform a Team Root Cause investigation. (2491809700203)

IE 22%

9704280010 970421
PDR ADOCK 05000249
S PDR

0084



USNRC
April 21, 1997

Page2

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,



J. Stephen Perry
Site Vice President
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office