

Commonwealth Edison Company  
Dresden Generating Station  
6500 North Dresden Road  
Morris, IL 60450  
Tel 815-942-2920



May 9, 1997

JSPLTR #97-0094

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Enclosed is Licensee Event Report 97-008, Docket 50-237, which is being submitted in accordance with 10CFR50.73(a)(2)(v), which requires the reporting of any event or condition that alone could have prevented the fulfillment of a safety function of structures or systems that are needed to: a) shutdown the reactor and maintain it in a safe shutdown condition, b) remove residual heat, c) control the release of radioactive material, or d) mitigate the consequences of an accident. In addition, it is being submitted in accordance with 10CFR50.73(a)(2)(i)(a), completion of a nuclear plant shutdown required by the Plant's technical specifications.

This correspondence contains the following commitments:

1. Straps will be installed on Unit 3 breaker auxiliary switches on Busses 33, 34, and 71, prior to startup from the current refueling outage (D3R14). (2371809700801)
2. On April 11, 1997, Golden Gate Switchboard Company issued a Notification of Potential Defect under the Requirements of 10CFR21.21(b). The final report will be reviewed by ComEd to address a permanent repair to the auxiliary switch mounting. (2371809700802)

9705140254 970509  
PDR ADOCK 05000237  
S PDR

140065




USNRC  
May 9, 1997

Page 2

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,

  
J. Stephen Perry  
Site Vice President  
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III  
NRC Resident Inspector's Office