

Commonwealth Edison Company
Dresden Generating Station
6400 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



May 15, 1997

JSPLTR #97-0097

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Enclosed is the first supplement to Licensee Event Report 96-022, Docket 50-237, which is being submitted pursuant to 10CFR50.73 (a)(2)(ii)(B), which requires the reporting of any event or condition that resulted in the nuclear power plant being in a condition that was outside the design basis of the plant.

This correspondence contains the following new or revised commitments:

1. A plant modification is being processed to replace the Emergency Core Cooling System suction strainers on both Units 2 and 3 with lower dP strainers. These new strainers are being installed in response to IE Bulletin 96-03. (Mod. No. M12-2(3)-96-006) (2371019600301 & 2371019600302)
2. A Training Request or Revision (TRR) has been written and will be submitted to the Engineering Training Committee to request additional training in the area of Engineering Design Specifications, appropriate review of vendor documents, including design calculations, test scope, and procedures to ensure that each item when delivered meets or exceeds the specified performance. Additionally, the proposed training would emphasize the importance of inter-disciplinary review of design specifications in projects where more than one discipline is involved. (237180960220101)

1/1
Lezz

9705220496 970515
PDR ADOCK 05000237
S PDR

220085




USNRC
May 16, 1997

Page 2

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


J. Stephen Perry For
Site Vice President
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office