



May 16, 1997

JSPLTR #97-0098

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Enclosed is Licensee Event Report 97-005, Do ket 50-249, which is being submitted in accordance with 10CFR50.73(a)(2)(i)(b), which requires the reporting of any operation or condition prohibited by Technical Specifications.

This correspondence contains the following commitments:

1. Dresden Engineering Surveillance 8300-20 will be revised to reflect proper sequencing of maintenance as well as instructions concerning as-found and preconditioning issues. (2371809700501)
2. Station battery testing and maintenance procedures will be reviewed to verify proper instructions concerning as-found requirements and preconditioning issues. (2371809700502)
3. A sample review of completed Electrical Maintenance work packages will be performed to verify compliance with Station policy concerning development and revisions to the packages. (2371809700503)
4. The last 250VDC and 125VDC battery discharge tests will be reviewed to verify compliance with as-found requirements and preconditioning issues. (2371809700504)
5. A sample review of Engineering letters will be performed to verify compliance with Station policy concerning development and revisions to procedures and work packages. (2371809700505)
6. The results of the root cause investigation and any significant corrective actions will be reported in a supplement to this LER. This supplement will include a review of personnel performance, and address prior similar occurrences and the effectiveness of their corrective actions. (2371809700506)

9705230075 970516
PDR ADOCK 05000249
S PDR




USNRC
May 16, 1997

Page 2

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


J. Stephen Perry
Site Vice President
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office