Commonwealth Edisor Empany Dresden Generating St. 6500 North Dresden Road Morris. IL 60450 Tel 815-942-2920



June 13, 1997

JSPLTR #97-0110

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Enclosed is Licensee Event Report 97-007, Docket 50-249, which is being submitted in accordance with 10CFR50.73(a)(2)(i)(b), which requires the reporting of any operation or condition prohibited by the plant's Technical Specifications.

This correspondence contains the following commitments:

- 1. Valve Serial Number BK-6526 will be disassembled, inspected, rebuilt, and retested. If the result of the disassembly and inspection does not confirm the cause indicated above, a supplement to this LER will be issued to provide the results of the inspection and proposed corrective actions. (2491809700701)
- 2. An evaluation will be performed of the Technical Specification setpoint tolerance of +/-1% for the Main Steam Safety Valves to determine if an expanded tolerance band can be adopted. (2491809700702)

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,

Y. Stephen Perry Site Vice President Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office

9706190263 970613 PDR ADDCK 05000249 S PDR Tiim im imimimimimimi