

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



June 18, 1997

JSPLTR #97-0108

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Enclosed is Licensee Event Report 97-012, Docket 50-237, which is being submitted in accordance with 10CFR50.73(a)(2)(iv), which requires the reporting of any event or condition that resulted in a manual or automatic actuation of any Engineered Safety Feature (ESF). Additionally, it is reported under 10CFR50.73(a)(2)(v), which requires the reporting of any event or condition that alone could have prevented the fulfillment of a safety function of structures or systems that are needed to: b) remove residual heat, or d) mitigate the consequences of an accident.

This correspondence contains the following commitments:

- 1) Install banana jacks at the terminal points required for the surveillance. (WR 960086891-01) (237-180-97-01203)
- 2) Establish a Peer Check Program within the Instrument Maintenance Department. (237-180-97-01201)
- 3) Train all Instrument Maintenance Technicians in self-checking to include demonstration on a "STAR" (Stop-Think-Act-Review) simulator. (237-180-97-01204)
- 4) Maintenance Staff will submit this event for inclusion into the required reading material for all maintenance departments. (237-180-97-01202)

111
Jew




9706250136 970618
PDR ADOCK 05000237
S PDR

USNRC
June 18, 1997

Page 2

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


J. Stephen Perry
Site Vice President
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office