

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



July 1, 1997

JSPLTR #97-0123

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555


Enclosed is the Licensee Event Report 97-013, Docket 50-237, which is being submitted pursuant to 10CFR50.73(a)(2)(v), which requires the reporting of any condition that could have prevented fulfillment of the safety function of a system needed to mitigate the consequences of an accident.


This correspondence contains the following completed corrective action:

The failed switch was replaced functionally verified, and the High Pressure Coolant Injection System (HPCI) operability was verified.

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


J. Stephen Perry
Site Vice President
Dresden Station



Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office

9707090258 970701
PDR ADOCK 05000237
S PDR



000130