

Commonwealth Edison Company  
Dresden Generating Station  
6500 North Dresden Road  
Morris, IL 60450  
Tel 815-942-2920



July 11, 1997

JSPLTR #97-0134

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Enclosed is the first supplement to Licensee Event Report 97-003, Docket 50-237, which is being submitted pursuant to 10 CFR 50.73(a)(2)(ii)(B) which requires the reporting of any event or condition that resulted in the nuclear power plant. In a condition that was outside the design basis of the plant.

This correspondence contains the following commitments:

1. To provide permanent corrective action, either over-pressure protection will be installed or penetration specific analytical considerations that confirm over pressurization is not a concern will be generated. (NTS #2371809700305S1 and 2371809700306S1)
2. Evaluate measured leakage rates from LLRT program until the long term resolution is carried out and confirm that the operability determination is not affected by the changes in measured LLRT leakage rates. (NTS #2371809700307S1)

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,

Stephen Perry  
Site Vice President  
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III  
NRC Resident Inspector's Office

9707220169 970711  
PDR ADOCK 05000237  
S PDR

