

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920

ComEd

July 15, 1997

JSPLTR #97-0135

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555


Enclosed is Licensee Event Report 97-003, Docket 50-249, which is being submitted in accordance with 10 CFR 50.73(a)(2)(v)(D), which requires the reporting of any event or condition that alone could have prevented the fulfillment of the safety function of a system required to mitigate the consequence of an accident.

This correspondence contains the following commitments:

- 1) The AOV Coordinator will review the Dresden Maintenance procedures to determine if any Copes-Vulcan reverse acting actuator procedures need to be revised. These procedures will be marked-up for revision and submitted to the Mechanical Maintenance procedure writer. (NTS #249-180-97-00301)
- 2) After completion of the above corrective action, the Mechanical Maintenance procedure writer will incorporate all comments and revise the procedures as required. (NTS # 249-180-97-00302)

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


J. Stephen Perry
Site Vice President
Dresden Station

1/1
Iezz

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office

9707220419 970715
PDR ADOCK 05000249
S PDR

