Ommonwealth Edisor Inpany Dresden Generating Station 6500 North Dresden Road Morris, II, 60450 Tel 815-942-2920



November 26, 1997

JSPLTR #97-0200

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Enclosed is an Licensee Event Report (LER) 97-012, Docket 50-249, which is being submitted in accordance with 10CFR50.73(a)(2)(i)(A), which requires the reporting of any nuclear plant shutdown required by the plant's Technical Specifications.

This correspondence contains the following commitments:

The Unit 3 Loop B Venturi flow element high pressure instrument piping support analysis will be evaluated to determine if improvements should be made to reduce vibration in the instrument line. (2491809701201)

If you have any questions, please contact Frank Spangenberg, Dresden Regulatory Assurance Manager at (815) 942-2920 extension 3800.

Sincerely,

J. Stephen Perry Site Vice President Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III NRC Resident Inspector's Office 1.622

9712010315 971126 PDR ADDCK 05000249 PDR

