

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



December 19, 1997

JSPLTR: #97-0214

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555


Enclosed is Licensee Event Report 97-013, Docket 50-249, which is being submitted in accordance with 10 CFR 50.73(a) (2) (v) (D), which requires the reporting of any event or condition that alone could have prevented the fulfillment of the safety function of a system required to mitigate the consequences of an accident.

This correspondence contained the following commitments:

1. The faulty auxiliary contacts will be sent to ComEd's central testing facility for analysis. Following the analysis, a supplemental LER will be provided with the identified root cause and any additional corrective actions. (2491809701301)

If you have any questions, please contact Frank Spangenberg, Dresden Regulatory Assurance Manager at (815) 942-2920 extension, 3800.

Sincerely,


J. Stephen Perry
Site Vice President
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office

9712300071 971219
PDR ADOCK 05000249
S PDR

