

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 801 WARRENVILLE ROAD LISLE, ILLINOIS 60532-4351

March 21, 1998

Mr. Oliver D. Kingsley
Commonwealth Edison Company
President, Nuclear Generation Group
ATT.: Regulatory Services
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

SUBJECT:

NOTICE OF VIOLATION AND INSPECTION REPORT NO. 50-237/98003(DRP):

50-249/98003(DRP)

Dear Mr. Kingsley:

The NRC performed an inspection at the Dresden Nuclear Power Station from January 12 through February 20, 1998. The purpose of the inspection was to assess routine performance. The enclosed report presents the results of that inspection.

During this inspection period, a safety-conscious approach characterized the overall conduct of activities at the Dresden Station. However, plant material condition and some maintenance activities continued to challenge the operators. Inadequate written work instructions and procedures impacted plant operations and maintenance. For example, an automatic reactor trip occurred during a surveillance test, and equipment was damaged due to installation of incorrect parts during maintenance of an emergency diesel generator.

Some events caused by the material condition issues, such as the occurrence of premature hydrogen recombination in the off-gas system, were repeat items, similar to those documented in prior NRC inspection reports. The unavailability of the high pressure coolant injection (HPCI) system has been a continuing problem at Dresden. During this inspection period, both the Unit 2 and 3 HPCI systems were again rendered inoperable due to equipment failures.

Based on the results of this inspection, the NRC determined that violations of NRC requirements occurred. The violations are cited in the enclosed Notice of Violation (Notice), and the circumstances surrounding the violations are described in detail in the subject inspection report. The violations all involved inadequate procedures or failure to follow procedures and represented a continuing trend of procedural and work instruction problems. In your response to the violations for inadequate work instructions, you are requested to address the overall issue of preparing high-quality work instructions.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. The NRC will use your response, in part, to determine whether further enforcement action is necessary to ensure compliance with regulatory requirements.

o70006

9803270168 980321 PDR ADDCK 05000237

PublicIE-01

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response will be placed in the NRC Public Document Room. الواز على الرابول الأنبور في المؤتري الذي الرؤة الوالو لأؤرة أولان البالا الأبار كالمرا بالساب بنسب

Sincerely,

Geoffrey E. Grant, Director Division of Reactor Projects

Docket Nos.: 50-237; 50-249 License Nos.: DPR-19; DPR-25

1.

Enclosures:

Notice of Violation

2. Inspection Report

> No. 50-237/98003(DRP); 50-249/98003(DRP)

cc w/encls:

M. Wallace, Senior Vice President

D. Helwig, Senior Vice President

G. Stanley, PWR Vice President -

J. Perry, BWR Vice President

D. Farrar, Regulatory Services Manager

I. Johnson, Licensing Director

DCD - Licensing

M. Heffley, Site Vice President

C. Howland, Station Manager Unit 1

P. Stafford, Station Manager Units 2 and 3

F. Spangenberg, Regulatory Assurance

Manager

Richard Hubbard

Nathan Schloss, Economist

Office of the Attorney General

State Liaison Officer

Chairman, Illinois Commerce

Commission

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response will be placed in the NRC Public Document Room.

المرازي المرازية والمرازية المرازية المرازية والمرازية المرازية المرازية والمرازية المرازية والمرازية والمرازية

Sincerely,

/s/ G. E. Grant

Geoffrey E. Grant, Director
Division of Reactor Projects

Docket Nos.: 50-237; 50-249 License Nos.: DPR-19; DPR-25

group the Markey is known to the first of place of the first of the fi

新闻, 1961年 1

The second of the control of the con-

Enclosures:

1. Notice of Violation

2. Inspection Report

No. 50-237/98003(DRP); 50-249/98003(DRP)

cc w/encls:

M. Wallace, Senior Vice President

D. Helwig, Senior Vice President G. Stanley, PWR Vice President

J. Perry, BWR Vice President

D. Farrar, Regulatory Services Manager

I. Johnson, Licensing Director

DCD - Licensing

M. Heffley, Site Vice President

C. Howland, Station Manager Unit 1

P. Stafford, Station Manager Units 2 and 3

F. Spangenberg, Regulatory Assurance

Manager

Richard Hubbard

Nathan Schloss, Economist

Office of the Attorney General

State Liaison Officer

Chairman, Illinois Commerce

Commission

## DOCUMENT NAME: G:\DRES\DRE98003.DRP

To receive a copy of this document, indicate in the box "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RIII PM N	RIII R.LEACH	RIII
NAME	RLerch:nmo	MRing Fort	GGrant CGG
DATE	03/20/98	03/2998	03/21/98() (

Distribution:

Docket File w/encls TSS w/encls PUBLIC IE-01 w/encls A. Beach w/encls
Deputy RA w/encls
RIII Enf. Coord. w/encls A. Beach w/encls DRP w/encls

DRS (2) w/encls Deputy RA w/encls
RIII PRR W/encls
RAC1 (E-Mail)
RIII Enf. Coord. w/encls
SRI Dresden w/encls
DOCDESK(E-Mail)
Project Mgr. NRR w/encls
DRP w/encls

RIII PRR W/encls
DCDESK(E-Mail)

Project Mgr., Unit 1, NRR w/encls
DRP w/encls RIII PRR W/encis