



Telegram

VEE316(2224)(1-036616C158)PD 06/07/73 2222 1973 JUN -7 PM 10: 26

ICS IPMVEIG MVN

07193 NL TDVE MORRIS IL 107 06-07 408PM CDM (OTHER THAN MONEY ORDERS)

PMS BOYCE GRIER

Is PHYSICAL DELIVERY requested? (YES-AGENT, NO-ADDRESSEE)

DIRECTOR DIVISION OF COMPLIANCE

AGENT SECTION ADDRESSEE SECTION

REGION 3 US ATOMIC ENERGY COMMISSION

Pr. & Name 312-858-2660

799 ROOSEVELT RD

Time Old 10304 TO OG By KK

GLEN ELLYN IL 60137

To be mailed or filed *mailed*

Attempts to deliver (Indicate DA or BY)

SUBJECT DPR19 DRESDEN NUCLEAR POWER STATION UNIT 2.

THIS WILL CONFIRM A CONVERSATION WITH MR MAURA OF YOUR OFFICE AT 1515 HOURS THIS DATE CONCERNING ISOLATION CONDENSOR MOTOR OPERATED VALVE 2-1301-1 WHICH WAS FOUND WITH THERMAL OVERLOADS TRIPPED. VALVE WAS IN ITS NORMAL OPEN POSITION SO ISOLATION CONDENSOR MOTOR FUNCTION WAS NOT EFFECTIVE. VALVE ISOLATE ON HIGH STEAM FLOW IN THE ISOLATION CONDENSOR AND THIS

SF-1201 (R5-69)

FUNCTION WAS NOT AVAILABLE. LAST SUCCESSFUL SURVEILANCE WAS MAY 14, 1973. ALL INDICATIONS WAS NORMAL FOR VALVE. THERMOL OVERLOAD WERE SET FOR MANUEL INSTEAD OF AUTOMATIC BUT CAUSE OF TRIP STILL UNDER INVESTIGATION.

W P WORDEN SUPERINTENDANT
DRESDON NUCLEAR POWER STATION
COMMONWEALTH EDDISON CO
RURAL ROUTE 1
MORRIS IL

Duplicates

SUN 11 1973

SF-1201 (R5-69)