

TWX INCOMING

Regulatory Docket File

Bethood
50-237 **1**

USAEC-HQS-GTWN

WU INFOASTER 1-044720C041 02/10/75

1975 FEB 10 AM 8 54

TLX WU PRESS WSH A

108

TWX 7108280475 USAEC-HQS-GTWN

U.S. ATOMIC ENERGY COMMISSION

TWX UNIT

SPL108 WAF153(1654)(2-032787E041)PD 02/10/75-1652

ICS IPMBNGZ CSP

8159424449 TDBN MORRIS IL 39 02-10 0452P EST

PMS J F OLARY, DIRECTOR, WUX



DIRECTORATE OF LICENSING U.S. ATOMIC ENERGY COMMISSION
WASHINGTON DC 20545

SUBJECT: DPR-19, DRESDEN NUCLEAR POWER STATION UNIT II.
THIS WILL CONFIRM THE CONVERSATION WITH MR JOHNSON OF YOUR OFFICE AT
1300 HOURS THIS DATE CONCERNING ADDITIONAL PIPE CRACK FOUND BY
ULTRA-SONIC TEST ON CORE SPRAY LOOP A IN THE SECTION OF PIPE DOWN
STREAM OF THE MANUEL VALVE IN THE DRYWELL. THE CRACK IS IN WELD
10-25 AT 12 OCLOCK AND IS APPROXIMATELY .3 INCHES LONG. THIS WILL BE
CORRECTED WHEN OTHER CORE SPRAY PIPING IS REPLACED LATER THIS MONTH.

B B STEPHENS SUPERINTENDENT DRESDEN NUCLEAR POWER STATION
COMMON WEALTH EDISON CO RRI MORRIS IL 60450

2305 EST

USAEC-HQS-GTWN



1561