



Telegram

DEB289 SSB447 DE CCA267

NOTED 0634P EST 07

(CH 059CC106267) PD=W U TELEG JOE

0630P EST 02/28/72

BOYCE GRIER,

ZCZC 009 GM NL PDF

DIRECTOR DIVN OF COMPLIANCE REGION 3 MORRIS ILL 28

US ATOMIC ENERGY COMMISSION

50-237

799 ROOSEVELT RD GLEN ELLYN ILL 60137

BT=DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2 THIS
 WILL CONFIRM CONVERSATION AT 1630 HRS. THIS DATE WITH
 H=DANCE REGARDING FAILURE OF A LIMIT SWITCH WHICH
 RESULTED IN AN UNOPERABLE REFUELING INTERLOCK. AT 17:00
 HRS FRIDAY 2/25/72 THE REACTOR REFUELING PLATFORM WAS
 MOVING OVER THE REACTOR CORE, PRIOR TO PICKING UP A
 FUEL BUNDLE. AS THE GRAPPLE WAS EXTENDED THE OPERATOR

WU 1201 (R 5-69)

OBSERVED THE ROD OUT PERMISSIVE LIGHT AND NOTED
 THAT THIS LIGHT DID NOT GO OUT AS IT SHOULD. THE
 OPERATION WAS TERMINATED. THE REFUELING PLATFORM TAKEN
 OUT OF SERVICE. REPAIRS MADE TO THE REFUELING PLATFORM
 TRAVEL LIMIT SWITCH. PLATFORM WAS OPERATIONAL BY 22:50
 HRS. THE SAME DAY.

W P WORDEN PLANT SUPT DRESDEN STATION

MAR 1 1972

TELEPHONE NO. 858-2660
 TELEPHONED TO. [Signature]
 TIME DELIVERED. 1:55P
 BY. [Signature] TO BE [Signature]

WU 1201 (R 5-69)

dupl