

Commonwealth Edison Company  
Dresden Generating Station  
6500 North Dresden Road  
Morris, IL 60450  
Tel 815-942-2920



April 19, 1999

JMHLTR: #99-0049

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

Dresden Nuclear Power Station, Unit 2  
Facility Operating License No. DPR-19  
NRC Docket No. 50-237

Subject: Licensee Event Report 1999-003-00, "Rod Block Monitor Inoperable due to Failed Diode"


The enclosed Licensee Event Report, which is a final report, describes the Rod Block Monitor inoperable due to a failed diode. This condition is being reported pursuant to 10CFR50.73(a)(2)(vii)(D), which requires the reporting of any event where a single cause or condition caused at least one independent train or channel to become inoperable in multiple systems or two independent trains or channels to become inoperable in a single system designed to mitigate the consequences of an accident.

The following actions were taken:

The diode was replaced per the station work request process.

If you have any questions, please contact Dale Ambler, Dresden Regulatory Assurance Manager at (815) 942-2920 extension, 3800.

Respectfully,

  
J. M. Heffley  
Site Vice President  
Dresden Nuclear Power Station

Enclosure

cc: Regional Administrator – NRC Region III  
NRC Senior Resident Inspector – Dresden Nuclear Power Station

9904270037 990419  
PDR ADDCK 05000237  
S PDR

JE22