

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I | L | D | R | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5

8 9 14 15 25 26 30 57 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0 1 | R | P | O | R | T | S | O | U | R | C | E | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 3 | 7 | 7 | 0 | 5 | 1 | 2 | 8 | 0 | 8 | 0 | 6 | 0 | 5 | 8 | 0 | 9

60 61 68 69 74 75 80

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Following a unit scram, double valve indication was observed on the HPCI inboard

0 3 | isolation valve. Upon trying to cycle the valve, the valve failed to close

0 4 | (T.S.3.7.D.1). The health and safety of the public was not endangered because the

0 5 | HPCI steam line was isolable via the outboard isolation valve and other ECCS systems

0 6 | were operable. This is the first occurrence of this type.

0 7 |

0 8 |

8 9

0 9 |

8

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

S | F | 11 | E | 12 | B | 13 | V | A | L | V | O | P | 14 | H | 15 | Z | 16

9 10 11 12 13 18 19 20

17 | LER/RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.

8 0 | 8 | 0 | 0 | 1 | 7 | 0 | 3 | L | 0

21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

B | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 23 | Y | 24 | N | 25 | L | 2 | 0 | 0 | 26

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The failure was due to a packing leak on the valve, causing water to enter the valve

1 1 | motor operator. The motor dried out and the valve was repacked and cycled

1 2 | successfully. No further action deemed necessary.

1 3 |

1 4 |

8 9

1 5 | FACILITY STATUS | % POWER | OTHER STATUS | 30 | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION | 32

D | 28 | 0 | 0 | 0 | 29 | N/A | Z | 31 | Operator Observation

8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY CONTENT | AMOUNT OF ACTIVITY | 35 | LOCATION OF RELEASE | 36

Z | 33 | Z | 34 | N/A | N/A

8 9 10 11 44 45 80

1 7 | PERSONNEL EXPOSURES | NUMBER | TYPE | DESCRIPTION | 39

0 | 0 | 0 | 37 | Z | 38 | N/A

8 9 11 12 13 80

1 8 | PERSONNEL INJURIES | NUMBER | DESCRIPTION | 41

0 | 0 | 0 | 40 | N/A

8 9 11 12 80

1 9 | LOSS OF OR DAMAGE TO FACILITY | TYPE | DESCRIPTION | 43

Z | 42 | N/A

8 9 10 80

2 0 | PUBLICITY | ISSUED | DESCRIPTION | 45

N | 44 | N/A | 8006170 519

8 9 10 80

NRC USE ONLY

NAME OF PREPARER: K. Zirwas

PHONE: X-529

68 69 80