



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

July 15, 1980

BBS Ltr. #80-594

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #80-27/01T-0, Docket #050-249, is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(i), performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses in the safety analysis report or technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition.

A handwritten signature in cursive script, appearing to read "B. B. Stephenson".

B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:nh

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

Handwritten: A002
5/11

8007220

577

S