



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

*Central
Files*

July 17, 1980

Mr. James G. Keppler, Director
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Dresden Station Units 2 and 3
Additional Response to IE
Bulletin 80-17
NRC Docket Nos. 50-237/249

Reference (a): J. G. Keppler letter to C. Reed dated
July 3, 1980

Dear Mr. Keppler:

This letter provides the Commonwealth Edison response to
Item 4 of IE Bulletin 80-17, which was transmitted by Reference
(a).

To comply with Items 4.a through 4.d, the following
procedures have been reviewed and revised:

DGP 2-3 - Unit 2/3 Reactor Scram

DGA 18 - Anticipated Transient with Incomplete Scram

DOP 1100-2 - Injection of Standby Liquid Control

All items discussed in Items 4.a through 4.d were addressed
as stated except Item 4.b.1. Item 4.b.1 has been addressed in
accordance with General Electric's letter to all BWR Operating
Station Superintendents, dated July 2, 1980. General Electric
recommended that for adjacent rods, a two (2) rod criteria be
applied as opposed to the five (5) rod criteria of IE Bulletin No.
80-17.

To comply with Item 4.e, the preliminary training
consisting of a written summary and our plans for the 30-day
training commitment was distributed on July 11, 1980 to all licensed
personnel and other associated management personnel.


8008010 096

JUL 21 1980

Mr. James G. Keppler, Director
July 17, 1980
Page 2

Please address any questions concerning this matter to this office.


Very truly yours,



Robert F. Janecek
Nuclear Licensing Administrator
Boiling Water Reactors

cc: Director, Division of
Reactor Operations Inspection

SUBSCRIBED and SWORN to
before me this 17TH, day
of July, 1980



Notary Public