

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 2 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5

0 1 L 0 5 10 0 0 2 3 7 0 8 2 9 8 0 0 9 1 9 8 0

0 2 During a Station Quality Assurance Audit, it was discovered that the diesel oil samples for the Unit 1 and Unit 2/3 diesel fire pump day tanks were not being taken on a monthly basis. This is contrary to T.S. 4.12.F.b. This event was of minimal safety significance, since both Unit 1 and Unit 2/3 fire diesel operability tests were performed three days prior with no anomalies noted. This is the first reported event of this type at Dresden.

0 9 SYSTEM CODE A B CAUSE CODE D CAUSE SUBCODE Z COMPONENT CODE Z Z Z Z Z Z COMP SUBCODE Z VALVE SUBCODE Z

17 LER/RO REPORT NUMBER 8 0 EVENT YEAR 0 3 2 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0 ACTION TAKEN G EFFECT ON PLANT Z SHUTDOWN METHOD Z HOURS 0 0 0 ATTACHMENT SUBMITTED N NPRO-4 FORM SUB N PRIME COMP SUPPLIER Z COMPONENT MANUFACTURER Z 9 9 9

1 0 The Tech. Spec. requirements to take oil samples from the fire diesel day tanks were not clearly defined on the surveillance sheets. Due to this oversight, diesel oil samples were taken but not always on a monthly basis. Oil samples were obtained and the surveillance sheets were revised to include Tech. Spec. sampling frequency. No further action is required.

1 5 FACILITY STATUS E % POWER 0 6 5 OTHER STATUS NA METHOD OF DISCOVERY B DISCOVERY DESCRIPTION Quality Assurance Audit

1 6 ACTIVITY CONTENT Z RELEASED OF RELEASE Z AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 TYPE Z DESCRIPTION NA

1 8 PERSONNEL INJURIES NUMBER 0 0 0 DESCRIPTION NA

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION NA

2 0 PUBLICITY ISSUED N DESCRIPTION NA

8009300478

NAME OF PREPARER M. Korchynsky

PHONE: X-523