



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

October 8, 1980

DJS LTR #80-154

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #80-16/01T-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(c), abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment. Revision 1 updates the cause description and corrective actions following receipt of failure analysis report.

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/lg

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Mgt. Branch
File/NRC

*A002
S.11*

8010210 655

5