



**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

DSB

September 26, 1980

DJS LTR #80-123

James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
u.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Revised Reportable Occurrence Report #79-017-01T, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems. This revision incorporates additional leakage on the 1601-23 & 24 valves.

D. J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS:lg

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Mgt. Branch  
File/NRC

A002  
S1/1

8010270380

5

OCT 21 1980