



Telegram

1974  
VEC320(2145)(1-048677C101)PD 04/11/74 2143 45

ICS IPMVEIA MVN

01424 IDVE MORRIS IL 111 04-11 422P CDT

PMS MR JAMES G KEPPLER

DIRECTOR DIRECTORATE OF REGULATORY OPERATIONS THAN MONEY ORDERS,

REGION 3

US ATOMIC ENERGY COMM

WUX

799 ROOSEVELT RD

GLEN ELLYN IL 60137

SUBJECT DPR-19

DRESDEN NUCLEAR POWER STATION UNIT 2.

IS PHYSICAL DELIVERED

AGENT SECT

abr. & Name

date dtd 4/12  
to be mailed or

attempts to deliver (indicate DA or BY)

RES-AGENT, NO-ADDRESSEE

SECTION

312-858-2660  
10-411 POC Ev 54

mail

THIS WILL CONFIRM A CONVERSATION WITH MR FISHBAUGHER OF YOUR OFFICE AT 1515 HOURS THIS DATE CONCERNING A CONDITION RELATING TO MAINTANANCE BEING PERFORMED ON TORUS TO DRY WELL VACCUUM

SF-1201 (RS-69)



Telegram

BREAKERS IN WHICH FOUR OF THE TWELVE VACCUUM BREAKERS WERE MADE INOPERABLE DURING A ROUTINE TOUR OF THE UNIT TWO REACTOR BUILDING THE ABOVE CONDITION WAS NOTED. IT WAS OBSERVED AT APPROXIMATELY 1530 HOURS APRIL 10 1974 CONDITION WAS IMMEDIATELY CORRECTED BY RETURNING ONE OF THE VACCUUM BREAKERS TO SERVICE. THE DETAILS AND CORRECTIVE ACTION WILL BE SUPPLIED IN A FOLLOWING TEN DAY LETTER

B B STEPHENSON

SUPERINTENDENT

DRESDON NUCLEAR POWER STATION

COMMONWEALTH EDISON CO

R.R. 1

MORRIS IL

APR 15 1974

Duplicate 13076

SF-1201 (RS-69)

8103030128

Regulatory

50-237

File Cy.

WESTERN UNION OUTGOING

*Beth*  
*008*

USAEC HQS GTWN

WU WSH

TLXA 747 WAB253(2145)(1-048677C101002)PD 04/11/74 2143

ICS IPMVEIA MVN

01425 TDVE MORRIS IL 111 04-11 422P CDT

PMS MR J F OLEARY

DIRECTOR DIRECTORATE OF LICENSING


US ATOMIC ENERGY COMM

WUX

WASHINGTON DC 20545

SUBJECT DPR-19

DRESDEN NUCLEAR POWER STATION UNIT 2.



1974 APR 11 PM 11 17

U.S. ATOMIC ENERGY COMM.  
T W X UNIT


THIS WILL CONFIRM A CONVERSATION WITH MR FISHBAUGHER OF YOUR OFFICE AT 1515 HOURS THIS DATE CONCERNING A CONDITION RELATING TO MAINTANANCE BEING PERFORMED ON TORUS TO DRY WELL VACCUUM BREAKERS IN WHICH FOUR OF THE TWELVE VACCUUM BREAKERS WERE MADE INOPERABLE DURING A ROUTINE TOUR OF THE UNIT TWO REACTOR BUILDING THE ABOVE CONDITION WAS NOTED. IT WAS OBSERVED AT APPROXIMATELY 1530 HOURS APRIL 10 1974 CONDITION WAS IMMEDIATELY CORRECTED BY RETURNING ONE OF THE VACCUUM BREAKERS TO SERVICE. THE DETAILS AND CORRECTIVE ACTION WILL BE SUPPLIED IN A FOLLOWING TEN DAY LETTER

B B TEPHENSON  
SUPERINTENDENT  
DRESDON NUCLEAR POWER STATION  
COMMONWEALTH EDISON CO

R.R.1  
MORRIS IL

NNNN

USAEC HQS GTWN  
1115P EDT  
WU WSH



3223

~~3223~~

*Dupe*  
*8103030128*

*13073*