

WESTERN UNION INCOMING

Regulatory

File Cy.

1973 DEC 4 PM 8 12

U.S. ATOMIC ENERGY COMM.
TWX UNIT

50-237

USAEC HQS GTWN
WU WSH

TLXA235 WAA243(1726)(1-028860C338002)PD 12/04/73 1721

ICS IPMVEIC MVN

03152 TDVE MORRIS IL 107 12-04 355PM CST

PMS MR J F O'LEARY


DIRECTOR, ~~DIRECTORAT OF~~ LICENSING

US ATOMIC ENERGY COMMISSION, WUX

WASHDC 20545

SUBJECT DPR 19 DRESDEN NUCLEAR POWER STATION UNIT 2

THIS WILL CONFIRM A CONVERSATION WITH MR MAURA OF YOUR OFFICE AT 1505 HOURS THIS DATE CONCERNING UNIT 2 TORUS HIGH LEVEL CONDITION CAUSED BY DRAIN FROM HPCI DRAIN LINE GOING TO TORUS. WHILE MAINTANANCE PATCHED STEAM DRAIN LINE TO CONDENSOR, HPCI STEAM DRAINS WERE LINED UP TO TORUS. OPERATIONS FAILED TO GET THE REPORT THAT REPAIRS WERE COMPLETE, AND FAILED TO NOTICE GRADUAL RISE IN TORUS LEVELS UNTIL ALARM SOUNDED BEYOND LIMITS AT 0715 TODAY. LINE WAS RESTORED TO NORMAL ON HPCI DRAIN AND TORUS LEVEL PUMPED DOWN TO




NORMAL LEVEL AT 0900.

W T WORDEN, SUPERINTENDENT DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON COMPANY RR 1 MORRIS ILLINOIS

NNNN

811P

USAEC HQS GTWN



WESTERN UNION INCOMING

8659

8103030345